

Monitor Horse Barn - 23509



A concerned couple came to us as their original contractor disappeared on them. Wouldn't return their phone calls or emails. They purposely sought out PermaBilt® based on our reputation and having been in the business since 1973. They wanted not only the quality put into the building but the service and reputation as well.

Our Building Representative met with them and immediately eased their concerns about getting their horse barn done. Working with them on their original design, the couple added an additional stall, a lean-to for family barbeques on the patio and a garage door to house their tractor and other equipment.

After having boarded their horse for several years, the couple was so thrilled to bring their animals home and not just any home but a brand new barn designed for their well-being and care.

Details:

- Building type: Monitor
- Building size: 53' x 36' x 25'
- Location: Brush Prairie, WA
- Concrete floor: 36'6" x 36' x 4" with fibermesh reinforcement and zip-strip crack-control
- Garage doors:
 - (2) 12' x 12' split sliding steel door with 2x cross hatching
 - 10' x 10' raised panel steel overhead door with Stockton lites
- Walk-in door:
 - (2) 3' x 6'8" PermaBilt® door 6 panel with 20" x 24" glass
 - Dutch Doors: (3) 4' x 8' red steel doors
- Stalls: (3) 12' x 12' PermaStalls® with 4' wide sliding door fronts; 3 feed doors and 2 removable dividers
- Windows:
 - (1) 4' x 1'6" vinyl windows with grids
 - (3) 3'6" x 3'6" vinyl windows with grids
 - (6) 3' x 2' vinyl windows with grids
 - (2) 4' x 5' vinyl windows with grids
- Second story floor: 24' x 24' with railings, #100
- Staircase: L-Shaped 13' x 4', #100
- Accessories:
 - (2) brown cupolas with horse and rooster weathervanes
 - (2) 22" octagon gable vents
 - 18" eave and gable overhangs